



CAUTION
CAUTION
CAUTION
CAUTION
CAUTION
CAUTION
CAUTION
CAUTION

An Accident Waiting to Happen



Wiring disconnected

Plastic tie found around switch arm



This Skyjack maintenance platform was tampered with to override critical safety features. The tampering allowed the unit to be driven at high speed with the platform extended.

Safety must never be jeopardized for the sake of expedience. Safety Devices are there for **YOUR** protection.